## PRIME MINISTERS SUITE ALTERATIONS - BUDGET ESTIMATE

Rates current at September 2005 Based upon budget estimate submitted by Rider Hunt 150905

Scheme A Replacement of existing smoked mirrors (damaged) with new clear mirrors Replacement of existing silk wall panels (damaged) Paint ceiling Modifications to Dining Room lighting Replacement of curtain Margins and adjustments Total Cost	\$17,000 \$22,000 \$ 2,000 \$ 7,500 \$ 4,500 \$35,900 <b>\$88,900</b>
Scheme B Replacement of existing smoked mirrors (damaged) with painted panels Replacement of existing silk wall panels (damaged) Paint ceiling Modifications to Dining Room lighting Replacement of curtain Margins and adjustments Total Cost	\$33,000 \$22,000 \$ 2,000 \$ 7,500 \$ 4,500 \$40,700 <b>\$109,700</b>
Sitting/ Dining Room  Demolition  Wall finishes  Floor finishes  Ceiling finishes  Electrical services alterations including lighting  Mechanical services alterations  Fire protection services alterations  Margins and adjustments  Total Cost	\$19,260 \$23,825 \$11,430 \$ 7,415 \$40,000 \$15,000 \$10,000 \$78,070 <b>\$205,000</b>

