

Inspection [REDACTED]

Last updated 20/12/2024

 [R017454](#)
[REDACTED]

- Basic Info

● Scope

● Inspection Brief

● Inspection Report

○ Conclusions

● Recommendations

Documents

▶ Save

Justification for this planned inspection

Eligible Inspection Scope

2019-20 AOP Inspection Topics (S&I)

3rd Party Equipment and Services

Assets and Ageing Facilities

Assurance of Performance Standards

2020-21 AOP Inspection Topics

COVID-19 management

KCI#73 - Oil Spill Response Capability Resilience

Facility Integrity (National Programmes)

Facility Integrity Management System - Onshore

Small bore piping, tubing and flexible hoses

Topsides Corrosion and Erosion

Topsides Maintenance System - Offshore

Topsides Maintenance System - Onshore

Topsides Pressure Integrity

Topsides Process Integrity

▶

Incident and Complaint Notifications

6341 OHS-DSCE-SDV failed to close on demand

6049 OHS - DODSI - Scaffolding tubes fell to deck below

5978 OHS-DODSI - Near miss event, Person incorrect access to a VFD cabinet of a starter motor.

5961 OHS - PL80 - Release of 500 litres petroleum product to deck

5862 OHS-DSCE-Failure of safety critical equipment to meet performance standards during testing

5810 OHS-DSCE-#3 Crane failed stall test

5803 OHS - DSCE - Blow down valve did not meet performance standard while testing

Planned Inspection Scope

Following up on Previous Recommendations

Verification of commitments regarding the recommendations from previous inspections and audits

Meet with HSRs - OHS

Consultation with Health & Safety Representatives and members of the workforce

Loss of Containment

Loss of Containment - SIF Assurance

Loss of Containment

Loss of Containment - Valve management CAR seal program

Inspection Scope

5961 OHS - PL80 - Release of 500 litres petroleum product to deck

5978 OHS-DODSI - Near miss event, Person incorrect access to a VFD cabinet of a starter motor.