

**Question on notice no. 391**

**Portfolio question number: SQ23-004944**

**2023-24 Supplementary Budget estimates**

**Rural and Regional Affairs and Transport Committee, Infrastructure,  
Transport, Regional Development, Communications and the Arts Portfolio**

**Senator Malcolm Roberts:** asked the Civil Aviation Safety Authority on 3  
November 2023—

Which five of the incidents in relation to question on notice answer SQ23-003791 was  
CASA not aware of?

**Answer —**

Please find answer attached

**Rural and Regional Affairs and Transport**

**QUESTION ON NOTICE**

**Supplementary Budget Estimates 2023 - 2024**

**Infrastructure, Transport, Regional Development, Communications and the Arts**

**Committee Question Number: 391**

**Departmental Question Number: SQ23-004944**

**Division/Agency Name: Agency - Civil Aviation Safety Authority**

**Hansard Reference: Written (03 November 2023)**

**Topic: CASA - Incidents mentioned in SQ23-003791**

**Senator Malcolm Roberts asked:**

Which five of the incidents in relation to question on notice answer SQ23-003791 was CASA not aware of?

**Answer:**

At the time of the response to Committee Question Number 193 (SQ23-003791) from the 2023-24 Budget Estimates hearing the Civil Aviation Safety Authority was not aware of the following incidents:

- 15 March 2023 – 737 Uluru/Ayers Rock overheat (this event has now been reported).
- 22 January 2023 – 737 engine over temperature (this event has now been reported)
- 11 May 2023 – 737 inflight shutdown due fuel leak (this event has now been reported)
- 8 March 2023 – 737 inflight shutdown due to oil bypass filter (this event has now been reported)
- October 2022 - Perth-Sydney. Engine Severe Damage (no report of this event has been received).