


**Attachment B (confirmed as correct table—L Hale & KGriffith 7.2.07)**



**Incidents involving damage to vehicles**

DATE	TIME	EVENT	BOLLARD EFFECTED	DAMAGE SUSTAINED TO BOLLARD(S) / ACTION TAKEN
3/1/2006	14:00	Vehicle hit card reader	Reps Entry	Card reader reassembled.
17/1/2006	15:00	Bobcat hit bollard	Ministerial Exit	Road loop adjusted. No damage to bollard
16/2/2006	13:30	Vehicle hit second set of Bollards	Reps Entry	Vehicle pulled away - slight damage to bollard. Replaced 'O' ring and bolts to plate that holds the 'O' ring
16/2/2006	14:00	Vehicle hit second bollard	Ministerial entry.	Vehicle pulled away - slight damage to bollard. Replaced 'O' ring and bolts to plate that holds the 'O' ring
4/5/2006	11:22	Vehicle tailgating impacted with Bollard	Ministerial entry.	Bollards cleaned. Replaced 'O' ring and bolts to plate that holds the 'O' ring
30/05/06	15:39	Vehicle tailgating impacted with Bollard	Ministerial entry.	Bollards cleaned. Replaced 'O' ring and bolts to plate that holds the 'O' ring
28/07/06	13:07	Bollards rose under vehicle	Senate entry	Tractor driver missed activating road loop and bollards rose as vehicle passed over. No damage to bollard
16/08/06	06:15	Commonwealth Car tailgating impacted with Bollard	Reps entry	Minor damage to bollard (scratches)
26/09/06	11:54	Vehicle impact - trying to enter via exit sliproad	Ministerial exit	No damage to bollard
17/10/06	23:01	Commonwealth car tailgating impacted with bollard	Reps exit	No damage to bollard
8/11/06	05:57	Vehicle hit second bollard	Senate entry	No damage to bollard. Software patch installed.