



Figure 1: The F-111 as many Australians know it




Figure 2: Diagram of F-111 fuel tank location



Figure 3: Inadequate use of Personal Protective Equipment



Figure 4: Confined work area



Figure 5: The newly constructed 'rag hanger' at Amberley





Figure 6: Working in the confines of a fuel tank with no Personal Protective Equipment

## Wing program- Inadequate PPE



Figure 7: Inconsistent use of Personal Protective Equipment



Figure 8: Coping with cramped working conditions



## Confines of aft tank- No PPE



Figure 9: Working in the confines of a fuel tank with no Personal Protective Equipment



Figure 10: The F-111 as many Australians know it